



## Product Discontinuance Notification

Date: 03/01/2021

### Overview

This notification serves the purpose of communication to Sales, Marketing, Customers and internally that OmniVision Technologies, Inc. (OVT) is discontinuing product(s) identified below immediately due to supplier's wafer capacity constrain.

In the past, OVT supported our customer(s) with the last time order (LTO) option for smooth transition. However, due to the aforementioned circumstances, OVT will not be able to offer LTO to our valued customer(s). OVT will try to fulfill existing order(s) with available material on-hand. OVT will not be able to guarantee quantity nor future shipment(s) and will no longer accept new orders for any product listed here. We sincerely apologize for any inconvenience that will arise from this notification.

### Product(s) Affected

<u>OVT P/N</u>	<u>OVT P/N</u>	<u>OVT P/N</u>	<u>OVT P/N</u>
OS02F10-A34A	OV07241-A32A	OV07960-E62H-PF	OV07962-E62A
OS04B10-A51A	OV07241-A32H	OV07960-E62H-RF	OV07962-E62T-PF
OS04B10-A51H	OV07241-A32H-PF	OV07960-E62N	OV07962-E62T-PH
OV02710-A68A	OV07725-G04A	OV07960-E62P	OV07962-E62T-RH
OV02710-A68A-1E	OV07725-V28A	OV07960-E62P-RH	OV07962-E62Y-PF
OV02710-A68A-PE	OV07725-V28T	OV07960-E62T-PF	OV07962-E62Y-PH
OV02710-A68A-PF	OV07740-A32A	OV07960-E62T-PH	OV07962-E62Y-RG
OV02715-A68A	OV07740-A32H	OV07960-E62T-RF	OV07962-E62Y-RH
OV02715-A68A-1E	OV07740-A32T	OV07960-E62T-RH	OV09155-V28A
OV02715-A68A-PC	OV07740-A32T-SS	OV07960-E62V-PF	OV09712-V28A-1D
OV02715-A68A-PE	OV07850-N02A	OV07960-E62V-PH	OV09728-A30A
OV02715-A68A-RC	OV07850-N02A-PE	OV07960-E62V-RF	OV09728-A30A-2A
OV02715-A68A-RE	OV07960-C48N	OV07960-E62V-RH	OV09755-H55A
OV04685-H67A	OV07960-C48P	OV07960-W20X	
OV04685-H67A-PF	OV07960-E62A		
OV04689-H67A-2A			

**Effective Date:** <03/01/2021>

**Last Time Order Date:** <N/A>

### Response

No response is required to this notification. For additional information regarding this notification, please contact your local OmniVision Technologies, Inc. Sales Representative.